



World's Largest Selection Of
USA made 550 Paracord
In 1,000 + Colors and
Patterns

Multi-tool Holder



paracordgalaxy.com

Materials:

About 8-10 feet of 550 paracord

About 2-3 feet of 550 paracord

Lacing needle or FID

{Cost for this project starts at \$5.98}



paracordgalaxy.com



paracordgalaxy.com

Step 1: Fold your long piece of paracord in half and loosely wrap your multi-tool around three sides with a little extra for a loop if desired. If you want to add a clip, thread it to the place shown.

Step 2: Fold both sides where your clip is and lay the cords with the working ends on the outside and the center fold in the middle.



paracordgalaxy.com

Step 3: Bring the right cord over the center cords and under the left cord.



paracordgalaxy.com

Step 4: Bring the left cord behind the center cords and up through the loop created by the right cord. Pull tight.



World's Largest Selection Of
USA made 550 Paracord
In 1,000 + Colors and
Patterns



paracordgalaxy.com

Step 5: Measure your center cords to be sure it is still long enough to wrap around your multi-tool. Continue the cobra weave by bringing the left cord over the center cords and under the right cord.



paracordgalaxy.com

Step 6: Bring the right cord behind the center cords and up through the loop created by the left cord. Pull tight.

paracordgalaxy.com



Repeat steps 3 through 6 until you have a small loop at the end and your weave is long enough to wrap around your tool.



paracordgalaxy.com

Attach a lacing need to your short piece of paracord. Toward the bottom of one side, insert the needle and thread the cord through as shown.



paracordgalaxy.com

Thread the cord through a hole across from the first.



paracordgalaxy.com

Move to the next hole up and continue weaving back and forth until you reach the top.



World's Largest Selection Of
USA made 550 Paracord
In 1,000 + Colors and
Patterns

paracordgalaxy.com



Once you reach the top, insert the cord through a hole on the opposite side and weave back and forth until you reach the bottom.



paracordgalaxy.com

When you have finished lacing both sides, trim and melt all excess cords.



paracordgalaxy.com